Attorney Docket No.: 2207/10753

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

**APPLICANTS** 

Sunil K. JAIN et al.

SERIAL NO.

09/821,115

**FILED** 

Patent

March 30, 2001

Certificate

SEP 2 3 2005

PATENT NO.

6,829,553 B2

of Correction

**ISSUED** 

December 7, 2004

**FOR** 

METHOD OF AND APPARATUS FOR MEASURING THE

CORRECTNESS OF AND CORRECTING AN AUTOMATIC

TEST ARRANGEMENT

GROUP ART UNIT:

2863

**EXAMINER** 

Kamini S. SHAH

M/S: CERTIFICATE OF CORRECTION BRANCH Commissioner for Patents P.O. Box 1450

Alexandria, VA 22313-1450

Certificate of Mailing

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: M/S: CERTIFICATE OF CORRECTION BRANCH, Commissioner for Patents, P.O. Box 1450, Alexandria, VA

22313-1450 on

Date: September 15, 2005

## REQUEST FOR CERTIFICATE OF CORRECTION

Dear Sir:

We have compared the above patent with the application as filed and have found errors in the printing of the patent. We respectfully request that the enclosed Certificate of Correction on Form PTO-1050 be issued correcting the mistakes set forth therein under authority of 35 U.S.C. §254. The exact column and line number where the errors occurred in the patent are listed on the enclosed certificate.

09/20/2005 ZJUHAR1 00000120 110600

6829553

01 FC:1811

100.00 DA

SEP 23 2005

The errors that appear in the patent are various typographical errors made by Applicant and therefore, a fee is required.

Please charge payment of the Certificate of Correction fee of \$100.00 to Deposit Account No. 11-0600. The Office is hereby authorized to charge any additional fees, or credit any overpayments, to Deposit Account No. 11-0600.

Respectfully submitted,

KENYON & KENYON

Dated: September 15, 2005

Sumit Bhattacharya (Reg. No. 51,469)

KENYON & KENYON 333 West San Carlos St., Suite 600 San Jose, CA 95110

Telephone:

(408) 975-7500

Facsimile:

(408) 975-7501

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

## CERTIFICATE OF CORRECTION

PATENT NO: 6,829,553 B2

DATED: December 7, 2004

INVENTOR(S): Sunil K. JAIN et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 8; Line 13 "by with the second output pin" should be --with the second output pin--

Column 8; Lines 50-51 "the instruction....determine the second" should be --the instructions determine the second--

Column 9; Lines 14-15 "the instruction when executed" should be --the instructions when executed--

Column 9; Line 21 "by with the second output" should be --with the second output--

MAILING ADDRESS OF SENDER:

Sumit Bhattacharya KENYON & KENYON 333 West San Carlos St. Ste 600 Telephone (408) 975-7950 FAX (408) 975-7501 PATENT NO. 6,829,553 B2

No. of additional copies



า

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.